BAREFOOT BAY RECREATION DISTRICT BREVARD COUNTY, FLORIDA ARCC COMMITTEE MEETING



625 Barefoot Blvd. - NAB Conference Room Agenda



05/09/2023

9:00 a.m.

- Call to Order
- Pledge of Allegiance
- Roll Call: Chair Gary Gresko, Vice Chair Paul Voit, Peter Carey, Tom Nelson, John Soulis and Alternates Tom O'Donnell and Deidre Sunter
- Chairperson's Report:
- Member's and other Reports:
- Approval of Minutes (04/25/2023)
- In Attendance: BOT Liaison Joseph Klosky and DOR/ARCC Administrative Assistant Sally-Ann Biondolillo

New Business:

(17) Consent Items:

Permit	Address	Renovation/Repair	Contractor/Builder
ARC23-000254	1073 BAREFOOT CIRCLE	Install inflatable hot tub in the rear of the home with a locking lid	Hajec, James T
ARC23-000255	1229 CALUSA DRIVE	Re-Roof - shingles	DC Roofing
ARC23-000256	458 MARLIN CIRCLE	Re-Roof - metal	DC Roofing
ARC23-000277	1023 SEBASTIAN ROAD	Construct 11' x 18' concrete pad between carport & shed	Cove Concrete & Company, LLC
ARC23-000278	434 SEA-GULL DRIVE	Re-Roof - metal	Rock Solid Roofing
ARC23-000280	829 VIREO DRIVE	Re-Roof - shingles	Melbourne Roofing
ARC23-000284	419 PAPAYA CIRCLE	Re-Roof - shingles	Superior One Roofing
ARC23-000285	933 VIREO DRIVE	Install replacement of 6' x 32' of Vince Barnett lattice around back patio	Vince Barnett
ARC23-000286	744 PERIWINKLE CIRCLE	Install 6' x 24' of lattice around back patio	Kolz, Douglas Glenn
ARC23-000288	627 PUFFIN DRIVE	Install 30 sq. ft. plastic shed anchored on the rear concret patio	Barry, Kevin e
ARC23-000289	726 OLEANDER CIRCLE	Re-Roof - metal	DC Roofing
ARC23-000290	937 LAUREL CIRCLE	Re-Roof - metal	Scozzari Roof Services
ARC23-000291	909 RED BUD ROAD	Re-Roof - metal	DC Roofing
ARC23-000292	325 KIWI DRIVE	Remove & replace windows & siding to match the home	McCarthy, Shawn

ARC23-000294	439 ROYAL TERN DRIVE	Re-Roof - shingles	Nail It Roofing
ARC23-000295	811 OLEANDER CIRCLE	Remove & replace vinyl siding, windows & door	Barefoot Services, Inc
ARC23-000297	1003 WREN CIRCLE	Install 8' x 14' concrete pad alongside of driveway	A Rated Concrete

(33) Other applications for review:

Permit	Address	Renovation/Repair	Contractor/Builder
ARC23-000253	937 FIR STREET	Install a 4' pool in the	Amos, Viktoria
ARC23-000257	712 AMARYLLIS DRIVE	Install and secure a 60 AG LP tank with exterior and interior piping	Como Oil & Propane
ARC23-000258	817 BEECH COURT	Install and secure a 60 AG LP tank with exterior and interior piping	Como Oil & Propane
ARC23-000259	694 PINEWOOD BOULEVARD	Install and secure a 60 AG LP tank with exterior and interior piping	Como Oil & Propane
ARC23-000260	950 CASHEW CIRCLE	Install and secure a 60 AG LP tank with exterior and inter	Como Oil & Propane rior piping
ARC23-000261	917 SPRUCE STREET	Install and secure a 60 AG	Como Oil & Propane
		LP tank with exterior and inter	rior piping
ARC23-000262	961 CASHEW CIRCLE	Install and secure a 60 AG LP tank with exterior and inter	Como Oil & Propane rior piping
ARC23-000263	809 JUNIPER DRIVE	Install and secure a 60 AG	Como Oil & Propane
		LP tank with exterior and inter	rior piping
ARC23-000264	1438 GARDENIA DRIVE	Install and secure a 60 AG LP tank with exterior and inter	Como Oil & Propane
ARC23-000265	837 WREN CIRCLE	Install and secure a 60 AG	Como Oil & Propane
ARC23-000203	657 WREN CINCLE	LP tank with exterior and inter	•
ARC23-000266	7365 BROWN ROAD	Install and secure a 60 AG LP tank with exterior and inter	Como Oil & Propane rior piping
ARC23-000267	825 THRUSH CIRCLE	Install and secure a 60 AG LP tank with exterior and inter	Como Oil & Propane rior piping
ARC23-000268	910 RED BUD ROAD	Install and secure a 60 AG LP tank with exterior and inter	Como Oil & Propane rior piping
ARC23-000269	1072 WREN CIRCLE	Install and secure a 60 AG LP tank with exterior and inter	Como Oil & Propane rior piping

Permit	Address	Renovation/Repair	Contractor/Builder
ARC23-000270	1002 ROBIN DRIVE	Install and secure a 60 AG LP tank with exterior and interior piping	Como Oil & Propane
ARC23-000272	902 RED BUD ROAD	Install and secure a 60 AG LP tank with exterior and interior piping	Como Oil & Propane
ARC23-000273	431 EGRET CIRCLE	Install and secure a 60 AG LP tank with exterior and interior piping	Como Oil & Propane
ARC23-000274	1024 WATERWAY DRIVE	Install and secure a 60 AG LP tank with exterior and interior piping	Como Oil & Propane
ARC23-000275	913 SEQUOIA STREET	Install and secure a 60 AG LP tank with exterior and interior piping	
ARC23-000276	1146 BAREFOOT CIRCLE	Install 4' chain link fence as per drawing with (2) 4 gates around back of property allowing access to utility boxes	Lane, David Arthur, II
ARC23-000279	434 SEA-GULL DRIVE	Replace A/C 3 ton unit with new pad	ARS Rescue Rooter
ARC23-000281	724 OLEANDER CIRCLE	Replace storm damaged 11' x 18' carport	Barefoot Services, Inc
ARC23-000282	1025 ORIOLE CIRCLE	New Home Package - Install new Skyline 24' x 52' home with 11' x 38' carport, 11' x 14' utility room, concrete steps, new concrete driveway and stucco skirting	Jason Miller
ARC23-000283	910 EVERGREEN STREET	Install 86' of 4' chain link fence with (2) gate allows access to all utility boxes	Bob Coleman
ARC23-000287	624 WEDELIA DRIVE	Extend driveway to 20' wide	A Rated Concrete
ARC23-000293	806 SAPODILLA DRIVE	Install 4' chain link fence in back yard with (1) 4' gate. Replace a window & storm door on utility room	SUHS, KENNETH & PAULINA
ARC23-000296	629 AMBER JACK COURT	Build screen enclosure on raised concrete under Existing pan roof	Barefoot Services, Inc.

Permit ARC23-000298	Address 1019 WREN CIRCLE	Renovation/Repair Install and secure a 60 AG LP tank with exterior and interior piping	Contractor/Builder Como Oil & Propane
ARC23-000299	1126 NAVAJO DRIVE	Install and secure a 60 AG LP tank with exterior and interior piping	Como Oil & Propane
ARC23-000300	965 LAUREL CIRCLE	Install and secure a 60 AG LP tank with exterior and interior piping	Como Oil & Propane
ARC23-000301	1118 WREN CIRCLE	Install and secure a 60 AG LP tank with exterior and interior piping	Como Oil & Propane
ARC23-000302	928 PERIWINKLE CIRCLE	Install and secure a 60 AG LP tank with exterior and interior piping	Como Oil & Propane
ARC23-000303	693 PINEWOOD BOULEVARD	Install and secure a 60 AG LP tank with exterior and interior piping	Como Oil & Propane

Closing Remarks: The next scheduled meeting will be Tuesday, May 23, 2023, at 9:00 am at 625 Barefoot Blvd., NAB Conference Room.

Discussion:

Adjournment:

Sally-Ann Biondolillo

Sally-Ann Biondolillo DOR/ARCC Administrative Assistant

Two or more Trustees of the Barefoot Bay Recreation District (BBRD) may attend this meeting.

Any person desiring to appeal any decision made by the ARCC Committee, with respect to any matter considered at this meeting or hearing, will need a record of the proceedings for such purposes, must ensure that a verbatim record and transcript of the proceedings, which record includes the testimony and evidence which the appeal is based. It shall be the responsibility of the person desiring to appeal any decision to prepare a verbatim record and transcript at his/her expense, as the district does not provide one. ATTN: PERSONS WITH DISABILITIES. In accordance with the Americans with disabilities Act and Sect.286.26, Florida Statutes, persons needing special accommodations to participate in this proceeding shall, at least 48 hours prior to the meeting, contact the DOR Enforcement Staff at (772) 664-3141.

BAREFOOT BAY RECREATION DISTRICT BREVARD COUNTY, FLORIDA ARCC COMMITTEE MEETING



625 Barefoot Blvd. - NAB Conference Room Agenda

04/25/2023

9:00 a.m.

- Call to Order: Meeting was called to order at 9:00 a.m.
- Pledge of Allegiance: Chairman Gary Gresko led the pledge of allegiance.
- Roll Call: Present: Chair Gary Gresko, Vice Chair Paul Voit, Peter Carey, Tom Nelson, John Soulis, and Alternate Deidre Sunter. Excused was Tom O'Donnell
- Chairperson's Report: The ARCC Guidelines are being presented to the BOT at 1:00 pm.
- Member's and other Reports: None
- Approval of Minutes: Minutes from 04/11/2023 were accepted and presented.
- In Attendance: Trustee Brinker and DOR/ARCC Administrative Assistant Sally-Ann Biondolillo

New Business:

Consent Items: Motion to approve Peter Carey, seconded by Tom Nelson, motion carried unanimously.

Permit	Address	Renovation/Repair	Contractor/Builder
ARC23-000239	409 AVOCADO DRIVE	Replace windows and door near FL room	WILL CALL TO SCHEDULE ORIENTATION
ARC23-000240	1066 BAREFOOT CIRCLE	Construct 11' x 32' concrete patio behind home	Hearndon Concrete
ARC23-000242	974 WATERWAY DRIVE	Install 4' x 15' concrete	CRAMER, KAREN
		pad along right side of driveway	
ARC23-000245	520 EGRET CIRCLE	Re-Roof - metal	DC Roofing
ARC23-000246	931 SPRUCE STREET	Construct a 48" x 60" landing w/step approx. 21" above rise - leaving 11' x 18' unobstructed carport	
ARC23-000247	434 SEA-GULL DRIVE	Re-Roof - membrane	Rock Solid Roofing
ARC23-000249	361 DOLPHIN CIRCLE	Replace stucco skirting stucco	Scott Thomas Stucco
ARC23-000250	428 KUMQUAT DRIVE	Construct 3' x 6 concrete pad behind the home & 3' x 32' sidewalk alongside of driveway	Ruben Jacobs
ARC23-000251	922 SPRUCE STREET	Re-Roof - metal	DC Roofing
ARC23-000252	801 LYCHEE DRIVE	Enclose existing screen room, install (4) windows, (1) door, siding to match the home	THERRIEN, MIKE & MARJORIE



Other applications for review:

Permit ARC23-000224	Address 905 PECAN CIRCLE	Renovation/Repair Install and secure a 60 gallon AG LP tank with exterior piping	Contractor/Builder Como Oil & Propane
Motion to approve by T	om Nelson, seconded by Peter	to connect to interior piping Carey, motion carried unanimous	slv
ARC23-000225	315 EGRET CIRCLE	Install and secure a 60 gallon AG LP tank with exterior piping to connect to interior piping	Como Oil & Propane
Motion to approve by T	om Nelson, seconded by Peter	Carey, motion carried unanimous	sly.
ARC23-000226	957 CASHEW CIRCLE	Install and secure a 60 gallon AG LP tank with exterior piping to connect to interior piping	Como Oil & Propane
Motion to approve by T	om Nelson, seconded by Peter	Carey, motion carried unanimous	sly.
ARC23-000227	1131 BAREFOOT CIRCLE	Install and secure a 60 gallon AG LP tank with exterior piping to connect to interior piping	Como Oil & Propane
Motion to approve by T	om Nelson, seconded by Peter	Carey, motion carried unanimous	sly.
ARC23-000228	914 WREN CIRCLE	Install and secure a 60 gallon AG LP tank with exterior piping to connect to interior piping	Como Oil & Propane
Motion to approve by T	om Nelson, seconded by Peter	Carey, motion carried unanimous	sly.
ARC23-000229	904 ORIOLE CIRCLE	Install and secure a 60 gallon AG LP tank with exterior piping to connect to interior piping	Como Oil & Propane
Motion to approve by T	om Nelson, seconded by Peter	Carey, motion carried unanimous	sly.
ARC23-000230	903 THRUSH CIRCLE	Install and secure a 60 gallon AG LP tank with exterior piping to connect to interior piping	Como Oil & Propane
Motion to approve by T	om Nelson, seconded by Peter	Carey, motion carried unanimous	sly.
ARC23-000231	624 ROYAL TERN DRIVE	Install and secure a 60 gallon AG LP tank with exterior piping to connect to interior piping	Como Oil & Propane
Motion to approve by T	om Nelson, seconded by Peter	Carey, motion carried unanimous	sly.
ARC23-000232	927 CYPRESS STREET	Install and secure a 60 gallon AG LP tank with exterior piping to connect to interior piping	Como Oil & Propane
Motion to approve by T	om Nelson, seconded by Peter	Carey, motion carried unanimous	SIV.

Motion to approve by Tom Nelson, seconded by Peter Carey, motion carried unanimously.

Permit ARC23-000233 Motion to approve by ⁻	Address 1114 NAVAJO DRIVE Fom Nelson, seconded by Pete	Renovation/Repair Install and secure a 60 gallon AG LP tank with exterior piping to connect to interior piping r Carey, motion carried unanimo	Contractor/Builder Como Oil & Propane usly.		
		r carey, motion carried anamino	usiy.		
ARC23-000234	860 PECAN CIRCLE	Install and secure a 60 gallon AG LP tank with exterior piping to connect to interior piping	Como Oil & Propane		
Motion to approve by	Tom Nelson, seconded by Pete	r Carey, motion carried unanimo	usly.		
ARC23-000235	704 LARK DRIVE	Install and secure a 60 gallon AG LP tank with exterior piping to connect to interior piping	Como Oil & Propane		
Motion to approve by	Tom Nelson, seconded by Pete	r Carey, motion carried unanimo	usly.		
ARC23-000236	633 HYACINTH CIRCLE	Install and secure a 60 gallon AG LP tank with exterior piping to connect to interior piping	Como Oil & Propane		
Motion to approve by	Tom Nelson, seconded by Pete	r Carey, motion carried unanimo	usly.		
ARC23-000237	889 CASHEW CIRCLE	Extend driveway 10' *not to exceed 24' wide	A Rated Concrete		
Motion to approve by P	Peter Carey, seconded by Paul V	oit, motion carried unanimously.			
ARC 23-000238	1060 BAREFOOT CIRCLE	Install 104' of 4' vinyl picket fence with (1) 5' gate and (1) 3' gate	Professional Grade Fence		
Motion to approve by I	Peter Carey, seconded by Tom I	Nelson, motion carried unanimou	sly.		
ARC23-000241	913 RED BUD ROAD	Repair storm damaged carport	Endeavor Construction		
Motion to approve by T	om Nelson, seconded by John S	Soulis, motion carried unanimous	ly.		
ARC23-000243	480 MARLIN CIRCLE	Install 155' of 4' black chain Link fence w/(2) 5' gates Around back & left side of Home	Palm Bay Fence		
Motion to approve by Tom Nelson, seconded by John Soulis, motion carried unanimously.					
ARC23-000244	926 SPRUCE STREET	Install 184' of 4' black chain link fence with (2) 5' gates	Palm Bay Fence		
Motion to approve by Joł	nn Soulis, seconded by Peter Care	y, motion carried unanimously.			
ARC23-000248	427 KUMQUAT DRIVE	Driveway Extension by 6' x 22' – not to exceed 24' wide	Ruben Jacobs		

Motion to approve by John Soulis, seconded by Peter Carey, motion carried unanimously.

Closing Remarks: The next scheduled meeting will be Tuesday, May 9, 2023, at 9:00 am at 625 Barefoot Blvd., NAB Conference Room.

Discussion: Tom Nelson and John Soulis will be excused on May 9th, 2023. Peter Carey will be excused on May 23rd, 2023, June 6th, and June 20th, 2023. Paul Voit will be excused on June 6th, and June 20th, 2023.

Adjournment: The meeting was adjourned at 9:31 am.

Sally-Ann Biondolillo

Sally-Ann Biondolillo DOR/ARCC Administrative Assistant

Two or more Trustees of the Barefoot Bay Recreation District (BBRD) may attend this meeting.

Any person desiring to appeal any decision made by the ARCC Committee, with respect to any matter considered at this meeting or hearing, will need a record of the proceedings for such purposes, must ensure that a verbatim record and transcript of the proceedings, which record includes the testimony and evidence which the appeal is based. It shall be the responsibility of the person desiring to appeal any decision to prepare a verbatim record and transcript at his/her expense, as the district does not provide one. ATTN: PERSONS WITH DISABILITIES. In accordance with the Americans with disabilities Act and Sect.286.26, Florida Statutes, persons needing special accommodations to participate in this proceeding shall, at least 48 hours prior to the meeting, contact the DOR Enforcement Staff at (772) 664-3141.



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: HAJEC, JAMES T

Acct#: 0871

Address: 1073 BAREFOOT CIRCLE

Block: 145 Lot: 6

Has permission to construct/alter or place: Install inflatable hot tub in the rear of the home with a locking lid

Contractor/Builder: <u>HAJEC, JAMES T</u>

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	<u>COMMENTS:</u>
,			
		·	
,		,	

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·		# <u>ARC23-000254</u> #23-000894



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: JOHNSON, SHARON

Address: 1229 CALUSA DRIVE

Acct#: <u>4507</u>

Address. 1229 CALOSA DRIVE

Block: 48 Lot: 18

Has permission to construct/alter or place: <u>Re-Roof - shingles</u>

Contractor/Builder: DC Roofing

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	COMMENTS:	DATE:	COMMENTS:
		·	
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	:	PERMIT: FILE:	# <u>ARC23-000255</u> #23-000895



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: STEVENS, CHRISTINE

Address: 458 MARLIN CIRCLE

Has permission to construct/alter or place: Re-Roof - metal

Contractor/Builder: DC Roofing

Signature of ARCC Member

Acct#: 3769

Block: 1 Lot: 21

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	:	PERMIT: FILE:	# <u>ARC23-000256</u> #23-000896



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: LECUYER, STEVEN M

Acct#: <u>2801</u>

Address: 1023 SEBASTIAN ROAD

Block: <u>15</u> Lot: <u>12</u>

Has permission to construct/alter or place: Construct 11' x 18' concrete pad between carport & shed

Contractor/Builder: Cove Concrete & Company

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	COMMENTS:	DATE:	COMMENTS:
,		·	
,	,		

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED		PERMIT: FILE:	# <u>ARC23-000277</u> #23-000981



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: ROYLO, GARRETT & LUCY

Address: 434 SEA-GULL DRIVE

Acct#: 4545

Block: 87 Lot: 18

Has permission to construct/alter or place: Re-Roof - metal

Contractor/Builder: Rock Solid Roofing

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
		·	

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	:	PERMIT: FILE:	# <u>ARC23-000278</u> #23-000982



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: BARNETT, KENNETH A

Address: 829 VIREO DRIVE

Acct#: <u>3276</u>

Block: <u>101</u> Lot: <u>15</u>

Has permission to construct/alter or place: <u>Re-Roof - shingles</u>

Contractor/Builder: Melbourne Roofing

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	COMMENTS:	DATE:	COMMENTS:

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	:	PERMIT: FILE:	# <u>ARC23-000280</u> #23-000984



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: AUGUST, JOHN W,II

Address: 419 PAPAYA CIRCLE

Acct#: <u>2812</u>

Block: <u>28</u> Lot: <u>10</u>

Has permission to construct/alter or place: <u>Re-Roof - shingles</u>

Contractor/Builder: Superior One Roofing

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	:	PERMIT: FILE:	# <u>ARC23-000284</u> #23-000988



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: LOUCKS, JOHN D, JR

Acct#: <u>0379</u>

Address: 933 VIREO DRIVE

Block: <u>104</u> Lot: <u>17</u>

Has permission to construct/alter or place: Install replacement of 6' x 32' of lattice around back patio

Contractor/Builder: Vince Barnett

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000285</u> #23-000989



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: KOLZ, DOUGLAS GLENN

Acct#: <u>4021</u>

Address: 744 PERIWINKLE CIRCLE

Block: 70 Lot: 4

Has permission to construct/alter or place: Install 6' x 24' of lattice around back patio

Contractor/Builder: KOLZ, DOUGLAS GLENN

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	COMMENTS:	DATE:	COMMENTS:
,		,,	
,	,		

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·		# <u>ARC23-000286</u> #23-000990



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: BARRY, KEVIN M

Acct#: <u>3871</u>

Address: 627 PUFFIN DRIVE

Block: <u>100</u> Lot: <u>9</u>

Has permission to construct/alter or place: Install 30 sq. ft. plastic shed anchored on the rear concrete patio

Contractor/Builder: <u>BARRY, KEVIN M</u>

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	COMMENTS:	DATE:	COMMENTS:
,		·	
,	,		

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·		# <u>ARC23-000288</u> #23-000992



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: WOJCIK, LEE JOSEPH

Address: 726 OLEANDER CIRCLE

Has permission to construct/alter or place: Re-Roof - metal

Contractor/Builder: DC Roofing

Signature of ARCC Member

Acct#: 3988

Block: 68 Lot: 34

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
,			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	:	PERMIT: FILE:	# <u>ARC23-000289</u> #23-000993



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: GENERAZIO, JOSEPH C

Address: 937 LAUREL CIRCLE

Acct#: 1005

Block: 114 Lot: 19

Has permission to construct/alter or place: Re-Roof - metal

Contractor/Builder: Scozzari Roof Services

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	COMMENTS:	DATE:	COMMENTS:

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	:	PERMIT: FILE:	# <u>ARC23-000290</u> #23-000994



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: BROWN, JESSICA NICOLE

Address: 909 RED BUD ROAD

Acct#: 3763

Block: 122 Lot: 9

Has permission to construct/alter or place: Re-Roof - metal

Contractor/Builder: DC Roofing

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	COMMENTS:	DATE:	COMMENTS:
,			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000291</u> #23-000995



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: MCCARTHY SHAWN

Acct#: <u>3086</u>

Address: 325 KIWI DRIVE

Block: 22 Lot: 8

Has permission to construct/alter or place: Remove & replace windows & siding to match the home

Contractor/Builder: MCCARTHY SHAWN

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
·			
·			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000292</u> #23-000996



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: SIMONTON, TERRY & DENISE

Address: 439 ROYAL TERN DRIVE

Has permission to construct/alter or place: Re-Roof - shingles

Contractor/Builder: Nail It Roofing

Signature of ARCC Member

Acct#: 1638

Block: 88 Lot: 3

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
,			
,			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	:	PERMIT: FILE:	# <u>ARC23-000294</u> #23-000998



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: CADE, MICHAEL SEAN

Acct#: <u>3755</u>

Address: 811 OLEANDER CIRCLE

Block: 56 Lot: 8

Has permission to construct/alter or place: Remove & replace vinyl siding, windows & door

Contractor/Builder: Barefoot Services, Inc.

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
·			
·			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000295</u> #23-000999



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: ANDERS MICHAEL

Acct#: <u>1431</u>

Address: 1003 WREN CIRCLE

Block: 137 Lot: 2

Has permission to construct/alter or place: Install 8' x 14' concrete pad along side of driveway

Contractor/Builder: <u>A Rated Concrete</u>

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
·			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000297</u> #23-001001



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: AMOS VIKTORIA

Acct#: 0583

Address: 937 FIR STREET

Block: 3 Lot: 16

Has permission to construct/alter or place: Install a 4' pool in the back fenced in yard

Contractor/Builder: AMOS VIKTORIA

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
·			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000253</u> #23-000893



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: BRYANT, CLINTON

Acct#: <u>4273</u>

Address: 712 AMARYLLIS DRIVE

Block: <u>73</u> Lot: <u>7</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
·			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000257</u> #23-000897



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: KNAPP, HOLLY ABELE

Acct#: 0001

Address: 817 BEECH COURT

Block: <u>105</u> Lot: <u>25</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	COMMENTS:	DATE:	COMMENTS:
,			
,			
,,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>05/09/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·		# <u>ARC23-000258</u> #23-000898



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: PELFREY, SHARON M

Acct#: <u>0718</u>

Address: 694 PINEWOOD BOULEVARD

Block: <u>104</u> Lot: <u>22</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
·			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·		# <u>ARC23-000259</u> #23-000900



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: **BLOMGREN**, JOHN KEITH

Acct#: <u>0790</u>

Address: 950 CASHEW CIRCLE

Block: <u>116</u> Lot: <u>5</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·		# <u>ARC23-000260</u> #23-000901



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: ESPOSITO, SUSAN J

Acct#: <u>0203</u>

Address: 917 SPRUCE STREET

Block: <u>4</u> Lot: <u>8</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
·			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000261</u> #23-000903



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: DUFFY PAUL

Acct#: <u>0442</u>

Address: 961 CASHEW CIRCLE

Block: <u>114</u> Lot: <u>68</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
,			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·		# <u>ARC23-000262</u> #23-000904



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: LAFFERTY, CYNTHIA

Acct#: 0230

Address: 809 JUNIPER DRIVE

Block: <u>110</u> Lot: <u>22</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	COMMENTS:	DATE:	COMMENTS:
,		·	
,	,		

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000263</u> #23-000906



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: <u>O'ROURKE, TERRIE A.</u>

Acct#: <u>3458</u>

Address: 1438 GARDENIA DRIVE

Block: <u>65</u> Lot: <u>13</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
·			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·		# <u>ARC23-000264</u> #23-000908



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: DRESSER, RALPH G

Acct#: <u>0669</u>

Address: 837 WREN CIRCLE

Block: <u>129</u> Lot: <u>3</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	COMMENTS:	DATE:	COMMENTS:
,		·	
,	,		

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·		# <u>ARC23-000265</u> #23-000909



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: LAMBUSTA, LAURA

Acct#: <u>1548</u>

Address: 7365 BROWN ROAD

Block: <u>94</u> Lot: <u>1</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
·			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED:			# <u>ARC23-000266</u> #23-000911



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: MAGE, CHRISTINE

Acct#: <u>0021</u>

Address: 825 THRUSH CIRCLE

Block: <u>130</u> Lot: <u>5</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	COMMENTS:	DATE:	COMMENTS:
,			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000267</u> #23-000912



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: SCHMOCK, WILLIAM O

Acct#: <u>3671</u>

Address: 910 RED BUD ROAD

Block: <u>123</u> Lot: <u>13</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
·			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000268</u> #23-000914



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: GRAY, DALE

Acct#: <u>1494</u>

Address: 1072 WREN CIRCLE

Block: <u>138</u> Lot: <u>30</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
,			
,			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED			# <u>ARC23-000269</u> #23-000916



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: BROEDEL, RICHARD A

Acct#: <u>1277</u>

Address: 1002 ROBIN DRIVE

Block: <u>143</u> Lot: <u>2</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	COMMENTS:	DATE:	COMMENTS:
,			
,			
		,	
,,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000270</u> #23-000917



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: STONE, HENRY P JR

Acct#: <u>3483</u>

Address: 902 RED BUD ROAD

Block: <u>123</u> Lot: <u>9</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
,			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000272</u> #23-000919



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: ROBERT & KAREN SHOUP REVOCABLE TRUST

Acct#: <u>2118</u>

Address: 431 EGRET CIRCLE

Block: <u>86</u> Lot: <u>16</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	COMMENTS:	DATE:	COMMENTS:
,		·	
,	,		

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000273</u> #23-000920



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: KOLZ, MARY A

Acct#: <u>0614</u>

Address: 1024 WATERWAY DRIVE

Block: <u>126</u> Lot: <u>55</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	<u>COMMENTS:</u>
,			
,			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·		# <u>ARC23-000274</u> #23-000921



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: DUNCAN KATHLEEN

Acct#: <u>1131</u>

Address: 913 SEQUOIA STREET

Block: <u>5</u> Lot: <u>5</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
,			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000275</u> #23-000922



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: LANE, DAVID ARTHUR, II

Acct#: 0119

Address: 1146 BAREFOOT CIRCLE

Block: <u>52</u> Lot: <u>15</u>

Has permission to construct/alter or place: Install 4' chain link fence as per drawing with (2) 4 gates around back of property allowing access to utility boxes

Contractor/Builder: LANE, DAVID ARTHUR,II

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	<u>COMMENTS:</u>
,		,	
,		·	
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·		# <u>ARC23-000276</u> #23-000980



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: ROYLO, GARRETT & LUCY

Address: 434 SEA-GULL DRIVE

Acct#: <u>4545</u>

Block: <u>87</u> Lot: <u>18</u>

Has permission to construct/alter or place: Replace A/C 3 ton unit with new pad

Contractor/Builder: ARS Rescue Rooter

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
·			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000279</u> #23-000983



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: BATSCH, FRANK M

Address: 724 OLEANDER CIRCLE

Acct#: <u>3920</u>

Block: <u>68</u> Lot: <u>33</u>

Has permission to construct/alter or place: Replace storm damaged 11' x 18' carport

Contractor/Builder: Barefoot Services, Inc.

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	COMMENTS:	DATE:	COMMENTS:
,			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000281</u> #23-000985



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: <u>VICKERS, LINDA & JOHN</u>

Acct#: <u>1353</u>

Address: 1025 ORIOLE CIRCLE

Block: <u>139</u> Lot: <u>13</u>

Has permission to construct/alter or place: <u>New Home Package - Install new Skyline 24' x 52' home with 11' x 38' carport, 11' x 14' utility</u> room, concrete steps, new concrete driveway and stucco skirting

Contractor/Builder: Jason Miller

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
,		·	
		·	

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·		# <u>ARC23-000282</u> #23-000986



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: ROOSA, JENNIFER AND JEREMY

Acct#: <u>3823</u>

Address: 910 EVERGREEN STREET

Block: <u>9</u> Lot: <u>23</u>

Has permission to construct/alter or place: Install 86' of 4' chain link fence with (2) gate allow access to all utility boxes

Contractor/Builder: Bob Coleman

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
·			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000283</u> #23-000987



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: MURPHY, EDWARD G

Address: 624 WEDELIA DRIVE

Acct#: <u>4243</u>

Block: <u>75</u> Lot: <u>13</u>

Has permission to construct/alter or place: Extend driveway to 20' wide

Contractor/Builder: <u>A Rated Concrete</u>

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	COMMENTS:	DATE:	COMMENTS:

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000287</u> #23-000991



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: SUHS, KENNETH & PAULINA

Acct#: <u>3002</u>

Address: 806 SAPODILLA DRIVE

Block: <u>18</u> Lot: <u>41</u>

Has permission to construct/alter or place: Install 4' chain link fence in back yard with (1) 4' gate. Replace a window & storm door on utility room

Contractor/Builder: <u>SUHS, KENNETH & PAULINA</u>

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
·			
,			
,		·	

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000293</u> #23-000997



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: ROSSETTI, DAVID

Acct#: <u>4805</u>

Address: 629 AMBER JACK COURT

Block: <u>11</u> Lot: <u>10</u>

Has permission to construct/alter or place: Build screen enclosure on raised concrete under existing pan roof

Contractor/Builder: Barefoot Services, Inc.

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
·			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·		# <u>ARC23-000296</u> #23-001000



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: ARNOLD CANDY

Acct#: <u>1671</u>

Address: 1019 WREN CIRCLE

Block: <u>137</u> Lot: <u>10</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
,			
,			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	:	PERMIT: FILE:	# <u>ARC23-000298</u> #23-001002



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: <u>APPIS, ANGELINE F</u>

Acct#: 0339

Address: <u>1126 NAVAJO DRIVE</u>

Block: <u>50</u> Lot: <u>30</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
·			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·		# <u>ARC23-000299</u> #23-001003



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: KULICZKOWSKI, AIMEE

Acct#: <u>0498</u>

Address: 965 LAUREL CIRCLE

Block: <u>114</u> Lot: <u>33</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
,			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·		# <u>ARC23-000300</u> #23-001004



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: KITCHEN, BARBARA

Acct#: <u>1160</u>

Address: 1118 WREN CIRCLE

Block: <u>144</u> Lot: <u>6</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
,			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000301</u> #23-001005



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: DEDREUX, LINDA S

Acct#: <u>2880</u>

Address: 928 PERIWINKLE CIRCLE

Block: <u>62</u> Lot: <u>15</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	COMMENTS:	DATE:	COMMENTS:
	,		

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·		# <u>ARC23-000302</u> #23-001006



ARCC PERMIT TO ERECT, PLACE OR ALTER HOME OR STRUCTURE

ARCHITECTURAL CONTROL COMMITTEE PERMIT

This is to certify that: BOANI, DJALMA

Acct#: 0501

Address: 693 PINEWOOD BOULEVARD

Block: <u>105</u> Lot: <u>100</u>

Has permission to construct/alter or place: Install and secure a 60 AG LP tank with exterior and interior piping

Contractor/Builder: Como Oil & Propane

Signature of ARCC Member

Signature of ARCC Member

Architectural Review Control Committee (A.R.C.C.) INSPECTION REPORT

DATE:	<u>COMMENTS:</u>	DATE:	COMMENTS:
·			
·			
,			

NOTE: CONSTRUCTION SHOULD BE COMPLETE WITHIN 120 DAYS. NORMALLY FIVE ROUTINE INSPECTIONS SHOULD BE MADE DURING THAT PERIOD.

DATE ISSUED:	<u>05/09/2023</u>	INSPECTOR:	Sally Biondolillo
DATE EXIPIRED:	<u>09/06/2023</u>	SIGNATURE:	
COMPLETED/PASSED	·	PERMIT: FILE:	# <u>ARC23-000303</u> #23-001007